

Oil Field Environmental Incident Summary

Incident: 20140905185210 **Date/Time of Notice:** 09/05/2014 18:52
Responsible Party: BAYTEX ENERGY USA LLC
Well Operator: BAYTEX ENERGY USA LLC
Well Name: LARSON 11-162-99H
Field Name: AMBROSE **Well File #:** 16794
Date Incident: 9/5/2014 **Time Incident:** 13:00 **Facility ID Number:**
County: DIVIDE **Twp:** 162 **Rng:** 99 **Sec:** 11 **Qtr:** NW NE
Location Description:

Submitted By: Randy Verret **Received By:**
Contact Person: Randy Verret
600 17TH STREET, SUITE 1600 S
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident Stuffing Box Leak

Release Contained in Dike Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.4	Barrels		
Brine	0.5	Barrels	0.4	Barrels		

Other

Description of Other Released Contaminant:

Not applicable

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Minimal

Areal Extent:

Impacted area on pad (overspray) approx. 40' x 50'/ approx. 12' x 12' area adjacent to well pad.

Potential Environmental Impacts:

Minimal- Most of overspray was confined to well pad

Action Taken or Planned:

Well shut-in & vacuum truck immediately deployed. Contaminated soil being excavated; reviewing trapper performance & source of leak out of containment at wellhead.

Wastes Disposal Location: All contaminated materials collected will be trucked to approved landfill for disposal.

Agencies Involved:**Updates**

Date: 9/26/2014 **Status:** Reviewed; Followup Required **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the well location as well as the neighboring well location. Followup is necessary to ensure that there weren't areas off the well pad affected by this spill.

Date: 10/29/2014 **Status:** Inspected **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10/29/2014.

Spill confined to area around wellhead.

No followup necessary.